





INDUSTRIAL NITRILE GLOVES

WIDTH SIZING

HOW TO MEASURE:

Measure from inside of thumb to outer edge of your dominant hand.

Note: Sizing chart serves as a guide only.



CIRCUMFERENCE SIZING

HOW TO MEASURE:

Measure around your dominant hand just below your knuckles. Reference the chart below to find your recommended size.

S	M	L	XL
8" 20cm	9" 23cm	10" 25cm	11" 28cm

USAGE INSTRUCTIONS

For single and transient use only. Wear and dispose of these in accordance with industry standards and best practices. Immediately discontinue use if damaged.

STORAGE

Store at temperatures less than 104°F (40°C). Open box should be shielded from exposure to direct sunlight and moisture.